

(1) OWNER: Name CAMINO VISTA WATER DIST Address
(2) LOCATION OF WELL: County ISLAND - SE 1/4 SE 1/4 Sec. 10 T. 30 N., R. 3E W.M. (WELL #5)
Bearing and distance from section or subdivision corner
(3) PROPOSED USE: Domestic [] Industrial [] Municipal [x] Irrigation [] Test Well [] Other []
(4) TYPE OF WORK: Owner's number of well #5
New well [x] Method: Dug [] Bored [] Deepened [] Cable [] Driven [] Reconditioned [] Rotary [x] Jetted []
(5) DIMENSIONS: Diameter of well 6 inches. Drilled 280 ft. Depth of completed well 280 ft.
(6) CONSTRUCTION DETAILS: Casing installed: " Diam. from ft. to ft. Threaded [] " Diam. from ft. to ft. Welded [x] 6 " Diam. from +1 ft. to 275 ft.
Perforations: Yes [] No [x] Type of perforator used SIZE of perforations in. by in. perforations from ft. to ft. perforations from ft. to ft. perforations from ft. to ft.
Screens: Yes [x] No [] Manufacturer's Name JOHNSON Type SS Model No. Diam. Slot size from ft. to ft. Diam. 5 3/8 Slot size .015 from 275 ft. to 280 ft.
Gravel packed: Yes [] No [x] Size of gravel: Gravel placed from ft. to ft.
Surface seal: Yes [x] No [] To what depth? 18 ft. Material used in seal BENTONITE Did any strata contain unusable water? Yes [] No [x] Type of water? Depth of strata Method of sealing strata off
(7) PUMP: Manufacturer's Name GRUNDOS Type SUB HP 3
(8) WATER LEVELS: Land-surface elevation above mean sea level 286.19 ft. Static level 226 ft. below top of well Date Artesian pressure lbs. per square inch Date Artesian water is controlled by (Cap, valve, etc.)
(9) WELL TESTS: Drawdown is amount water level is lowered below static level Was a pump test made? Yes [x] No [] If yes, by whom? ADLER Yield: 39 gal./min. with 3 ft. drawdown after 4 hrs. Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)
Time Water Level Time Water Level Time Water Level
Date of test Bailer test gal./min. with ft. drawdown after hrs. Artesian flow g.p.m. Date Temperature of water Was a chemical analysis made? Yes [x] No []

(10) WELL LOG: Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
TAN SANDY CLAY	0	10
SAND & GRAVEL	40	195
BLUE CLAY	195	220
SILTY BLUE SAND	220	232
BLUE CLAY	232	260
SILT BLUE SAND w/WOOD	260	268
BLUE CLAY	268	272
SAND GRAVEL w/WATER	272	280

RECEIVED
JAN 14 1988
DEPARTMENT OF ECOLOGY
NORTHWEST REGION
Work started 11-21, 19 Completed 11-24, 1988
WELL DRILLER'S STATEMENT:
This well was drilled under my jurisdiction and this report true to the best of my knowledge and belief.
NAME CAMINO WELL DRILLING (Person, firm, or corporation) (Type or print)
Address 215 N. GOODRICH RD. C.I.
[Signed] [Signature] (Well Driller)
License No. 1525 Date 19